





116,706 Miles
Chevy 4500
Air conditioning
Duramax Diesel engine
4600# front axle rating
9600# rear axle rating
LT 225/75R16 front tires in good condition
LT 225/75R16 Rear tires in good condition
Stainless wheel covers

Electronic siren Air horn on front of body Whelen LED Light package To View More Photos, technical specs, and more visit www.firetruckresource.com

AMBULANCE

