



1988 Ford Marion

1988 Ford Chassis
 14,600 miles
 2 man cab
 Air Conditioning
 Ford Diesel
 Automatic transmission
 Front Axle: 9,000# Rear Axle: 17,500#
 Front tires: 10 R22.5 Good Condition
 Rear Tires: 10 R22.5 Good Condition
 Crew area with (3) seating locations (heated)
 Marion aluminum walk-around body
 Belly compartments for cribbing
 7.5KW Onan diesel generator
 3,000 watt command light tower
 (4) 500 watt telescoping lights
 (3) electric cord reels
 Six bottle 5,000 psi cascade system with fill panel
 (3) air reels
 Code 3 electronic siren
 Code 3 Force 4XL halogen lightbar
 Directional arrow board
 OAL: 27Ft.



To View More Photos, technical
 specs, and more visit
www.firetruckresource.com

FTR
 FIRE TRUCK RESOURCE