



## 1999 E-One 105' Platform

21,959 Miles  
 (6) Total Cab Seats, (3) SCBA Seats  
 Air Conditioning (Doesn't Work)  
 ISM Cummins Engine, 450 HP, 5,400 Hours  
 Allison Transmission  
 Front Axle: 21,000#  
 Rear Axle: 52,000#  
 Front Tires: 425/65 R22.5 Good Condition  
 Rear Tires: 12 R22.5 Good Condition  
 Stainless Steel Wheel Covers  
 Q2 & Electronic Siren  
 Air Horns in Bumper  
 E-One Super Smart Batter Charger  
 Air Shoreline in Cab Step  
 Hale 1500 GPM Pump  
 Current Pump Test  
 (2) 1 1/2" Preconnects  
 2 1/2" Discharges (2) Left, (2) Right  
 Stainless Pump Panel in Good Condition  
 250 Gallon Poly Water Tank  
 Side Discharge Panel in Good Condition  
 OAL: 46'  
 OAH: 11' 11"  
 Aerial Test 12/2020  
 Hydraulic AMPS, 8 KW  
 (2) 1,000 Watt, (2) 500 Watt 120 Volt Scene Lights  
 Federal Signal Halogen and Strobe Lights  
 (2) Unity's 12 Volt Scene Lights (rear)  
 Lens in Good Condition



To View More Photos, technical  
 specs, and more visit  
[www.firetruckresource.com](http://www.firetruckresource.com)

