



## 1994 HME Alexis Pumper Rescue

54,918 Miles  
(6) Cab Seats (5) SCBA Seats  
Air Conditioning  
Detroit Series 60 Engine, 450 HP, 2,837 Hours  
Allison Transmission  
Front Axle: 18,000#  
Rear Axle: 24,000#  
Front Tires: 315/80R22.5 Good Condition  
Rear Tires: 11R22.5 Good Condition  
Stainless Steel Wheel Covers  
Electronic Siren  
Air Horns in Bumper  
Vanner Battery Charger  
Hale 1500 GPM Pump  
Current Pump Test  
(2) 1 1/2" Preconnects  
(2) Left, (2) Right, (1) Rear 2 1/2" Discharges  
1 1/2" Discharge on Bumper  
1" Booster Reel in Rear  
Master Intake Valves (Each Side)  
1,000 Gallon Poly Tank  
(1) 2 1/2" Tank Fill  
OAL: 32'  
OAH: 116" To Top of Ladders  
AMPS 6KW Generator  
(2) 500 Watt 120 Volt Scene Lights  
12 Volt Scene Lights, (1) on Each Side

Equipment To Stay:  
24' & 14' Ladders  
Cord Reel  
Electronic Siren  
Generator  
(2) 6" Hard Suction Hose  
Chrome Caps



To View More Photos, technical specs, and more visit  
[www.firetruckresource.com](http://www.firetruckresource.com)

**FTR**  
FIRE TRUCK RESOURCE